

DELTA HEAT




# DELTA HEAT 26" PEDESTAL BASE ASSEMBLY INSTRUCTION


PN: 18657A 07/13




A: HEX SCREW, 1/4-20 X 5/8
(16x)




B: CASTER WITH BRAKES
(2x)



C: CASTER WITHOUT BRAKES
(2x)



D: SCREW, 10-24 X 1/2 TYPE-F
(23x)



E: PLASTIC BUSHING
(2x)



F: 10-32 x 1/2 MACHINE SCREW
(8x)





G: 8-32 x 3/8 MACHINE SCREW
(4x)





H: 8-32 KEP NUTS
(4x)


TOOLS REQUIRED:
1. 7/16 WRENCH OR 7/16 SOCKET WRENCH
2. ELECTRIC SCREWDRIVER










D



D
D






D
D



E
E









D






D






D






D



D


F




D


D


H
G